



2822 Sable Mill Rd., Jeffersonville, IN 47130
Toll: (877) 338-9403 Fax: (812) 288-7971
<http://www.1stsourceproducts.com>

Learn how to measure a Hex Bore

(Think of a hex as a clock – DO NOT measure flat to flat.)

1. Place one caliper end at the groove (not at the flat) at 6:00
2. Place the other caliper end at the groove at either 10:00 or 2:00

